



Docent (fysik)

European Patent Attorney Medl. av Svenska Patentombudsföreningen

I, Dr. Bertil Grennberg, registered European Patent Attorney, hereby attest as follows. I am conversant with the English language and have controlled the correctness of the English translation as hereto affixed and hereby attest that it is a true translation of a text in Swedish entitled:

Universell bandelement-modul för två eller fler membranbredder med optimerat flöde och drivning

said text being presented to me by Mr. Bo Bengtsson as a true copy of a US patent application filed by himself in the Swedish language in the USPTO and identified as Serial 09/961,149.

Uppsala, Sweden, the fifth day of December 2001


It is hereby certified that Dr Bertil Grenn berg has/here personally signed this document.

Uppsalg, Sweden, 10 Dec.e

Johan Östlund

Bertil Grennberg





COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
WASHINGTON, D.C. 2023I
www.usdfo.gov

APPLICATION NUMBER

FILING/RECEIPT DATE

FIRST NAMED APPLICANT

ATTORNEY DOCKET NUMBER

09/961.149

09/24/2001

Bo Bengtsson

CONFIRMATION NO. 5367

FORMALITIES LETTER

OC000000006935894

Bo Bengtsson c/o P. Glaser Raverns grand 18 B, 1tr Uppsala, 753 19 SWEDEN

N

Date Mailed: 10/19/2001

NOTICE TO FILE MISSING PARTS OF NONPROVISIONAL APPLICATION

FILED UNDER 37 CFR 1.53(b)

Filing Date Granted

An application number and filing date have been accorded to this application. The item(s) indicated below, however, are missing. Applicant is given **TWO MONTHS** from the date of this Notice within which to file all required items and pay any fees required below to avoid abandonment. Extensions of time may be obtained by filing a petition accompanied by the extension fee under the provisions of 37 CFR 1.136(a).

• The application was filed in a language other than English. Applicant is required to provide an English translation of the specification and a statement that the translation is accurate. (See 37 CFR 1.52(d)).

The application is informal since it does not comply with the regulations for the reason(s) indicated below.

The required item(s) identified below must be timely submitted to avoid abandonment:

- Substitute drawings in compliance with 37 CFR 1.84 because:
 - drawing sheets do not have the appropriate margin(s) (see 37 CFR 1.84(g)). Each sheet must include a top margin of at least 2.5 cm. (1 inch), a left side margin of at least 2.5 cm. (1 inch), a right side margin of at least 1.5 cm. (5/8 inch), and a bottom margin of at least 1.0 cm. (3/8 inch);
 - drawing figures contain text that is not in English (including, for example, a flow chart that was originally not in English that has been marked up to include the English text) see 37 CFR 1.84(p)(2) and 37 CFR 1.52(d)(1);

A copy of this notice <u>MUST</u> be returned with the reply.

Customer Service Center

